

<u>PTO Code</u> 017AE 	<u>Pump Side Connection Type of PTO</u> 6 Keyway Milling Spindle Output 6x21x25 - UNI	<u>Main Transmission Model</u> BMC 415 JAC LC 6 T 540 B JAC 1008	Gear Type : Left Helix PTO Type : Double Thread Torque Nm : 200 Power Kw : 21 Output Ratio 1000 Rpm : 1:1,04 Mounting Location : Left Side Control System : Pneumatic PTO Shaft Rotation : Rihgt — (Pump Shaft Rotation : Left) Weight Kg. : 10,50	
<u>PTO Code</u> 374AE 	<u>Pump Side Connection Type of PTO</u> 6 Keyway Milling Spindle Output 6x21x25 - UNI	<u>Main Transmission Model</u> BMC 415 JAC LC 6 T 55	Gear Type : Left Helix PTO Type : Double Thread Torque Nm : 170 Power Kw : 17 Output Ratio 1000 Rpm : 1:1,04 Mounting Location : Left Side Control System : Pneumatic PTO Shaft Rotation : Rihgt — (Pump Shaft Rotation : Left) Weight Kg. : 9,50	
<u>PTO Code</u> 287AE 	<u>Pump Side Connection Type of PTO</u> 6 Keyway Milling Spindle Output 6x21x25 - UNI	<u>Main Transmission Model</u> BMC 415 EURO 4 FOTON BJ 1069 JAC LC 6 T 46	Gear Type : Flat PTO Type : Double Thread Torque Nm : 160 Power Kw : 17 Output Ratio 1000 Rpm : 1:1,33 Mounting Location : Left Side Control System : Pneumatic PTO Shaft Rotation : Rihgt — (Pump Shaft Rotation : Left) Weight Kg. : 12,50	
<u>PTO Code</u> 332AE 	<u>Pump Side Connection Type of PTO</u> 6 Keyway Milling Spindle Output 6x21x25 - UNI	<u>Main Transmission Model</u> BMC 415 EURO 4 FOTON BJ 1069 JAC LC 6 T 46	Gear Type : Left Helix PTO Type : Double Thread Torque Nm : 170 Power Kw : 17 Output Ratio 1000 Rpm : 1:0,81 Mounting Location : Left Side Control System : Pneumatic PTO Shaft Rotation : Rihgt — (Pump Shaft Rotation : Left) Weight Kg. : 15,00	